

Ravensberger Schmierstoffvertrieb GmbH
Postfach 1163
33819 Werther
Tel.: 05203/9719-0
Fax.: 05203/9719-40 / 41

-Certificate / ProductInformation-

RAVENOL MARINE Power Trim & Steering Fluid

Art. 1234100

Description:

RAVENOL MARINE Power Trim & Steering Fluid is a high quality hydraulic oil based on specially selected solvent refined base oils.

It is particularly characterized by a high and stable viscosity index and reliable corrosion protection. Effective additives provide an excellent wear protection even under extreme loads. The behaviour towards sealing materials is neutral.

Application Directions:

RAVENOL MARINE Power Trim & Steering Fluid is an excellent product for lubrication of hydraulics in the marine area.

May not be used if in the hydraulic systems are silver and / or silver-plated construction and operating elements present.

Quality Classification:

RAVENOL MARINE Power Trim & Steering meets the following specifications and classifications: OMC, VOLVO PENTA, Mercruiser, YANMAR

Technical Characteristics:

RAVENOL MARINE Power Trim & Steering Fluid offers:

- A high and stable viscosity index
- Excellent protection against wear
- Widest possible protection against corrosion
- A very good air and water separation to prevent foaming
- A neutral attitude towards plastic and seals
- A very low pour point

Technical Values:

Characteristics	unit	data	test according to	
Colour		blue	visual	
Density	at 20°C	kg/m ³	857	EN ISO 12185
Viscosity	at 40°C	mm ² /s	32,0	DIN 51 562
	at 100°C	mm ² /s	6,3	DIN 51 562
Viscosity index			152	DIN ISO 2909
Flash point (COC)	°C		215	DIN ISO 2592
Pour point	°C		-39	DIN ISO 3016
TBN	mg KOH/g		0,4	DIN ISO 3771
Sulphated ash	%wt.		0,06	DIN 51 575

All indicated data are approximate values and are subject to the commercial fluctuations.

To the best of our knowledge all information reflects the current state of findings and our development. Subject to change. Any reference to DIN standards are solely for product description purposes and do not represent a guarantee. If problems occur please consult a technician.

06.11.14